
Figure 3: The pultrusion process



Filament dispensing Fibreglass rovings and matting

Forming process Shapes material

entering the die

Resin saturation Resin added

to the glass

Curing process Heated die

Cutting Diamond-

impregnated

saw blade